

IED Report

CLASSIFICATION: **SECRET** ~~REL TO~~
USA, ACGU
TRACKING NUMBER: **20111114092038SNA0132
647260** DATE DISCOVERED: **2011-Nov-14 09:20**
CALL SIGN: **Jester 1-3** REPORTING UNIT: **Not Reported**
PRIMARY SAFE AREA(MGRS): **38SNA0150146959** SECONDARY SAFE AREA(MGRS): **Not Reported**
MGRS: **38SNA0132647260** EVENT TYPE: **Not Reported**

COALITION:		CIVILIAN:		HOST NATION:	
KIA:	WIA:	KIA:	WIA:	KIA:	WIA:
0	0	0	0	0	0

Equipment Used

Equipment Used 1

EQUIPMENT USED TYPE: **Crew** EQUIPMENT USED NAME: **Not Reported**

Team Data

SERVICE AFFILIATION: **USA**
EOD NOTIFICATION: **2011-Nov-14 09:25**
EOD FOB DEPARTURE: **2011-Nov-14 09:50** EOD SCENE ARRIVAL: **2011-Nov-14 10:25**
EOD SCENE DEPARTURE: **2011-Nov-14 11:31** EOD MISSION COMPLETE: **2011-Nov-14 12:10**

Site Data

SITE MARKED: No
MARKING DETAILS: Not Reported
CIVILIAN ACTIVITY: Normal Activity
REFERENCE POINT: Unknown
AIMING POINT DETAILS: Not Reported
FIRING POINT DETAILS: Not Reported
FIRING POINT MGRS: Not Reported
LIGHT CONDITIONS: Daytime
WEATHER: Not Reported
ROUTE PATROL: Not Reported
LAST TIME ROUTE CLEARED: Not Reported
ANALYSIS: Not Reported

Devices

Device

1

DEVICE DESCRIPTION: TL assesses the EFP to be dual array, utilizing approximately 10 inch steel plates with approximately 40lbs of UBE.
MGRS: Not Reported
PLACEMENT: Concealed - Debris/Rubble Pile **LOCATION:** Road - Right Side
CONTAINER: Unknown **CONTAINER SUB-TYPE:** Not Reported
HOW DEVICE WAS FOUND: Detonation **WHO FOUND DEVICE:** Not Applicable
ACTION TAKEN: Post Blast
EXPLOSIVE EFFECT: Blast

MAIN CHARGE CONFIGURATION: Directional-EFP

CASUALTIES: No SUICIDE DEVICE: No FIRST RESPONDER TARGETED: No

POST BLAST: Yes PARTIAL BUILD: No

Targets

TARGET PRECEDENCE: Primary

AFFILIATION: Coalition

COUNTRY: USA - UNITED
STATES

TARGET TYPE: Military

DETAILS: Patrol

INTENDED EFFECT: Anti-Armor

DESCRIPTION: 4 Caiman Patrol.

Initiators

Not Reported

Munitions

Not Reported

****SIGACT CLOSED****

SIGACT Report

TITLE: (EXPLOSIVE HAZARD) IED EXPLOSION RPT (Directional IED) 2/B/2-8 CAV, 1-1 CAV IVO (ROUTE MSR TAMPA): 0 INJ/DAM

TRACKING NUMBER: 20111114092038SNA0132647260

REPORT PRECEDENCE: Routine

CLASSIFICATION: ~~SECRET~~

RELEASABILITY: ~~REL TO USA, FVEY~~

REPORTING UNIT NAME: USD-C G3 SIGACT
MANAGER

REPORT SOURCE: Coalition

SPOT Section

UNIT NAME INVOLVED: 2/B/2-8 CAV, 1-1 CAV **CALL SIGN:** Not Reported

TYPE OF INVOLVED UNIT: CF **INVOLVED UNIT ACTIVITY:** Other

INCIDENT REPORTED BY: Coalition Forces **BATTLESPACE LEAD:** Coalition

TIP REPORTED BY: Not Reported **DTG CREATED (LOCAL):** 2011-11-14 10:57:13

DTG OF INCIDENT (LOCAL): 2011-11-14 09:20:00 **DTG UPDATED (LOCAL):** 2011-11-15 16:34:12

Location

MGRS: 38SNA0132647260

ROUTE: MSR TAMPA

Events

EVENT TYPE: Explosive Hazard

MODES OF ATTACK: Directional IED

EVENT CATEGORY:	IED Explosion
PRIMARY INTENDED OUTCOME:	Anti-Personnel
SUICIDE?:	No
EFFECTIVE HIT?:	No

COORDINATED ATTACK: No

COMPLEX ATTACK: No

COUNTER ATTACK: No

MEDEVAC REQUESTED: No

BLOWN IN PLACE: No

SUMMARY: USF REPORT

AT 14 0920 NOV 11, AN IED DETONATED ON A 2/B/2-8 CAV C-IED PATROL TRAVELING SOUTH ON MSR TAMPA. 2-8 CAV REPORTED NO CASUALTIES AND MINOR DAMAGE QRF AND EOD RESPONDED TO THE SITE TO CONDUCT PBA. (b)(1)1.4g

(b)(1)1.4g WHEN PBA WAS COMPLETE ALL ELEMENTS RTB. AT APPROXIMATELY 1900, 1-1 AAB REPORTED THAT EOD ASSESSED THAT THE IED WAS AN EFP.

EOD ASSESSMENT: ON 140935CNOV2011 752/1/3 MANEUVERED TO CONDUCT POST BLAST ANALYSIS ISO 2-8 CAV, BANDDOG GREEN 1 IVO 38S NA 01326 47260. EOD ARRIVED ON SITE, LINKED UP WITH ON-SCENE COMMANDER, CONDUCTED 5/25'S AND SET UP SAFE AREA. OSC STATED THAT WHILE TRAVELING SOUTH ON RTE TAMPA AN IED DETONATED ON THE WEST SIDE OF THE ROAD AND STRUCK THEIR LEAD VEHICLE. NO INJURIES TO PERSONNEL, VEHICLE RECEIVED RIGHT SIDE REAR DAMAGE TO (b)(1)1.4g. EOD TEAM PERFORMED ARMORED RECONNAISSANCE OF THE SITE AND IDENTIFIED A LARGE BLAST SEAT APPROXIMATELY 2.5 METERS FROM THE ROAD NEAR A LARGE DIRT PILE. EOD TL DISMOUNTED AND PERFORMED RECONNAISSANCE OF THE AREA. TEAM TOOK PHOTOS AND MEASUREMENTS FROM THE SCENE. EOD TEAM LOCATED TWO SEPARATE IMPACT POINTS ON THE VEHICLE. (b)(1)1.4g

(b)(1)1.4g

(b)(1)1.4g CRATER MEASURES APPROXIMATELY 5FT X 6FT WITH A DEPTH OF 26 INCHES. NO EXPLOSIVE HAZARDS WERE FOUND. EOD TEAM RTB.

TL ASSESSES

(b)(1)1.4c, (b)(1)1.4g

(b)(1)1.4c, (b)(1)1.4g

1-1 AAB S2 ASSESSMENT:

(b)(1)1.4c

(b)(1)1.4c

EOD ASSESSED TODAY'S EVENT TO BE (b)(1)1.4c
THE DEVICE WAS MOST LIKELY HASTILY EMLACED (NOT BURIED)
AND IN FRONT OF A SMALL DIRT MOUND BY A MOBILE
EMPLACEMENT TEAM WHEN NO USF OR ISF WERE PRESENT. WHILE
EOD, ROUTE CLEARANCE, AND BANDOG COMPANY WERE AT THE
BLAST SEAT, THEY WERE UNABLE TO IDENTIFY ANY COMMAND WIRE
TYPE INITIATOR. WE ASSESS THIS (b)(1)1.4g TO HAVE
BEEN MOST LIKELY RC ARMED AND PIR INITIATED. WHILE IT IS ALSO
POSSIBLE THIS DEVICE COULD HAVE BEEN TOIR ARMED AND PIR
INITIATED, WE DO NOT ASSESS THIS TO BE THE CASE DUE TO (b)(1)1.4c

(b)(1)1.4c

DUE TO THE TYPE OF DEVICE AND THE HISTORIC IED ACTIVITY IN THIS
AREA, WE ASSESS THAT THIS ATTACK WAS CARRIED OUT BY (b)(1)1.4c

(b)(1)1.4c

(b)(1)1.4c PLANNING RKG-3 AND IED ATTACKS ON U.S.
FORCES AS THEY WITHDRAW FROM IRAQ. THE GROUP IS LED BY

(b)(1)1.4c

USD-C G-2 ASSESSMENT: CONCURS WITH 1/1 CAV S2 ASSESSMENT

AND HAS NO FURTHER INFORMATION REGARDING THIS ATTACK.

BDA:

1 X VEHICLE DAMAGED (MINOR)

ENEMY:			COALITION:		
KIA:	WIA:	DET:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CIVILIAN:			HOST NATION:		
KIA:	WIA:	ABD:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CCIR Status

SUMMARY: USF-I DCG(O) IR 17: Any attack utilizing RKG-3, EFP, SVBIED and/or PBIED

GROUP: USD-C G3 SIGACT MANAGER

Capture Details

Casualty Details

Target(s) of Attack

PRECEDENCE: Primary

TYPE: Coalition

AFFILIATION: Coalition

SECT: Unknown

DETAILS: Other

NATIONALITY: IRAQ

STATUS: Unaffected

DESCRIPTION: Not Reported

Indirect Fire Information

Vehicle/Convoy Details

NUMBER OF VEHICLES: 0

DISTANCE BETWEEN VEHICLES: 0 Meters

CONVOY SPEED: 0 MPH

NEAREST ECM DIST TO IED: 0 Meters

NEAREST ECM DIST TO VEHICLE STRUCK: 0 Meters

OTHER COUNTERMEASURES ON VEHICLE STRUCK: Not Reported

VEHICLE SUMMARY: Not Reported

DRUGREP Details

FACILITY TYPE: Not Reported

Drugs Found

Chemicals Found

Equipment Found

--	--

Reintegration Details

REINTEGRATION OPEN: No

REINTEGRATION OPEN COMMENTS: No

NUMBER OF REINTEGRATEES: 0

	FOLLOW UP DATES	COMPLETED	COMPLETED DATE
VETTING DATE:	Not Reported	No	Not Reported
COMMUNITY TALK DATE:	Not Reported	No	Not Reported
REINTEGRATION DATE:	Not Reported	No	Not Reported
7 DAY FOLLOW UP:	Not Reported	No	Not Reported
30 DAY FOLLOW UP:	Not Reported	No	Not Reported
60 DAY FOLLOW UP:	Not Reported	No	Not Reported
90 DAY FOLLOW UP:	Not Reported	No	Not Reported
180 DAY FOLLOW UP:	Not Reported	No	Not Reported

REINTEGRATION CLOSED: No REINTEGRATION CLOSED REASON: Not
Reported

REINTEGRATION CLOSED COMMENTS: No



USD-C

(752ND / 1 / 3)

140925CNOV11

2-8 CAV BAND

1/1 CAV
SUPPORTED BCT

(b)(3), (b)(6)

TEAM LEADER

1

ON SCENE COMM

38SNA0148046977
MGRS GRID LOCATION

MS . TAM' A
MSR

South

DIRECTION OF

Blast
TYPE OF REPORT

EVENT CATEGORY

Other

METHOD OF EM

SIGACT #: 20111114092038SNA0132647260

CIDNE #: BLAST-20111114092538SNA0148046977

CCIR: DCG-O 12, 17 USD-C 18

	<u>CF</u>	<u>LN</u>	<u>IA/IP/NP</u>	<u>E</u>	<u>U.S. Civilian</u>	<u>Coalition</u>
KIA	0	0	0	0	0	0
WIA	0	0	0	0	0	0

USCENTCOM FOIA 17-0112

085 0

~~SECRET//REL TO USA, ACCU~~



USD-C

Convoy

(b)(1) 1 4g



USD-C

Aerial / Map View of Site



Time

EOD Notification:
EOD FOB Departure:
EOD Scene Arrival:
EOD Scene Departure:
EOD Mission Complete:






~~SECRET//REL TO USA, ACQU~~

USD-C

Scene Diagram



~~SECRET//REL TO USA, ACQU~~



USD-C

Narrative / Background

(UNCLASSIFIED //~~FOUO~~) On 140935CNOV2011 752/1/3 maneuvered to conduct Post Blast Analysis 8 CAV, Banddog Green 1 IVO 38S NA 01326 47260. EOD arrived on site, linked up with On-Scene Commander, conducted 5/25's and set up safe area. OSC stated that while traveling south on RTE an IED detonated on the west side of the road and struck their lead vehicle. No injuries to personnel vehicle received right side rear damage to MEAP and body. EOD Team performed armored reconnaissance of the site and identified a large blast seat approximately 2.5 meters from the road large dirt pile at known grid. EOD TL dismounted and performed reconnaissance of the area. EOD took photos and measurements from the scene. EOD .ea. located two separate impact points on vehicle, the impact area on the [redacted] (b)(1)1.4g Evidence shows that the IED was [redacted] (b)(1)1.4c approximately 10 inches in diameter with an estimated weight of 40lbs of UBE. Crater measures approximately 5ftx6ft with a depth of 26 inches. No explosive hazard found. EOD Team RTB. MC: 141215CNOV11.



USD-C

EOD Team Leader Observations

<u>Initiation Type</u>	<u>Initiator</u>	<u>Main Charge</u>	<u>Container</u>
Unknown	Unknown	Directional-EFP	Unknown
Improvised:			

(UNCLASSIFIED //~~FOUO~~) TL assesses th [REDACTED] (b)(1)1.4c, (b)(1)1.4g
(b)(1)1.4c, (b)(1) with approximately 40lbs of UBE.



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene

~~UNCLASSIFIED // FOUO~~



EAST FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112

091 0

~~SECRET//REL TO USA, ACGU~~



~~SECRET//REL TO USA, ACCU~~

USD-C

Photographs of Scene

~~UNCLASSIFIED // FOUO~~



NORTH FROM GRID 38 S NA 01480 46977

USCENTCOM FOIA 17-0112

092 0

~~SECRET//REL TO USA, ACCU~~



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene

~~UNCLASSIFIED // ECHO~~



EAST FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112

093 0

~~SECRET//REL TO USA, ACGU~~



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene

~~UNCLASSIFIED // ECHIRO//FOUO~~



SOUTH FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112

~~SECRET//REL TO USA, ACGU~~


094 0



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene



BLAST SEAT AT GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112

095 0

~~SECRET//REL TO USA, ACGU~~



USD-C

Photographs of Scene

(b)(1)1.4g



USD-C

Photographs of Scene

(b)(1)1.4g

(b)(1)1.4c, (b)(1)1.4g



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene

~~SECRET // REL TO USA, ACGU~~



(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112

~~SECRET//REL TO USA, ACGU~~

098 0



~~SECRET//REL TO USA, ACCU~~

USD-C

Photographs of Scene

~~SECRET//REL TO USA, ACCU~~



(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112

099 0

~~SECRET//REL TO USA, ACCU~~



~~SECRET//REL TO USA, ACCU~~

USD-C

Photographs of Scene

(b)(1)1.4g

(b)(1)1.4g

~~SECRET//REL TO USA, ACCU~~



USD-C

Photographs of Scene

(b)(1)1.4g

(b)(1)1.4g



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene



(b)(1)(4g)

~~SECRET//REL TO USA, ACGU~~



~~SECRET//REL TO USA, ACCU~~

USD-C

Photographs of Scene

~~SECRET//REL TO USA, ACCU~~



OTHER EFP IMPACT POINT WITH SCALE



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene

~~SECRET//REL TO USA, ACGU~~



OTHER IMPACT AREA FROM EFP ON THE RIGHT SIDE REAR

(b)(1)(4g)

~~SECRET//REL TO USA, ACGU~~



~~SECRET//REL TO USA, ACGU~~

USD-C

Photographs of Scene



(b)(1)1.4g

SMALL FRAGMENTATION HOLE ON FRONT RIGHT SIDE

(b)(1)1.4g

~~SECRET//REL TO USA, ACGU~~



~~SECRET//REL TO USA, ACQU~~

USD-C

Photographs of Scene



FRAGMENTATION HOLE IN (b)(1)1.4g WITH SCALE